

ATTESTATION



Product Service

This is to confirm that

Dongguan Anci Electronic Technology Co., Ltd.

1-2/F., Building A, and 1F., Building B, No.11, Zongbu 2nd Road,
Songshan Lake High-Tech Industrial Development Zone, Dongguan,
Guangdong, China

has been accepted by

TÜV SÜD Certification and Testing (China) Co., Ltd. Shenzhen Branch

Building 12 & 13, Zhiheng Wisdomland Business Park, Guankou
Erlu, Nantou, Nanshan District, 518052, Shenzhen, P. R. China
(On behalf of TÜV SÜD Certification and Testing (China) Co., Ltd.
Guangzhou Branch & TÜV SÜD Hong Kong Ltd.)

for cooperating in on-site witness projects according to the following standards:

EN IEC 55015, EN IEC 61000-3-2, EN 61000-3-3, EN 61547, ETSI
EN 300 328, ETSI EN 301 489-1, ETSI EN 301 489-17, EN IEC
62311, EN 62479, EN 50663, EN 50665

This document states that the above named company is included in the TÜV SÜD PRODUCT SERVICE GROUP (TÜV SÜD) Listing of Recognized Laboratories and is qualified in compliance with the TÜV SÜD External Test Laboratory (ETL) program for the mutually agreed product categories and/ or standards.

As far as the testing facilities meet the relevant requirements of this program and the tests of the projects are conducted under the supervision and witness of the engineer(s) of TÜV SÜD Certification and Testing (China) Co., Ltd. Shenzhen Branch or other 2 TÜV SÜD offices in South China Region, the test results can be used as a basis for a TÜV SÜD certification.

Attestation No.: SCN1467
Expiration Date: 2024-09-24

TÜV SÜD China – South Region

KM Lam

Date of Issuance: 2023-09-25

*TÜV SÜD makes no representations or warranties, express or implied, regarding any aspect of this Laboratory's business or services or that this Laboratory's services will achieve any specific results in any TÜV SÜD investigation. TÜV SÜD does not assume or undertake to discharge any liability of this Laboratory or any other party. TÜV SÜD assumes no liability which may result directly or indirectly from assessment or Certification of this Laboratory, the conduct or a failure to conduct inspections, incorrect Certification, nonconformity or failure to discover nonconformity with Program Requirements, cancellation of this Attestation or withdrawal of this Laboratory's inclusion from any TÜV SÜD PRODUCT SERVICE GROUP Listing or Directory prior to the expiration date of this Attestation. This Laboratory bears sole responsibility for its provision of services.